



Issue: The metal bottles do not fit into the bottle holder

Explanation: If the bottles do not fit correctly, it may be due to improper alignment or debris in the mounting points.

Solution:

1. Ensure that the **pistons are fully retracted** before inserting the bottles.
2. Clean the bottle holder contact points with a dry cloth to remove any debris.
3. Verify that you are using **compatible 2.5 kg bottles, 1:1 ratio**.
4. If the bottles still do not fit, refer to the **User Manual, section "Bottle Installation"**.

© 2025 FugaExpert Solutions, S.L. All rights reserved. The information contained in this manual is for informational and technical purposes only. FugaExpert Solutions, S.L. is not responsible for any damage or harm resulting from improper use, incorrect installation, or inadequate maintenance of the FX5PRO COMPAQ equipment. The manufacturer reserves the right to make changes or improvements to the product without prior notice.